

## Wall Jib Crane Underbraced 180° PMI

## Product information

The headroom is the main asset of the PMI. Its I beam profile allows to consider installation of a hoist with electric or manual steering. The PMT are delivered with standard mounting brackets and our mounting kits KITFIX (optional) ensure safe anchorages for specific supports.

A full range of accessories is available.

## Options

- Hoist power supply cable + lockable main switch
- Standpipe
- Rotation slowing device (adaptable without welding or mechanical intervention)
- Hot dip galvanizing (contact us)
- Rotation stops to weld onto the assembly
- Single or multipositions rotation lock
- Outdoor use
- Motorization
- Electric or manual hoist

| Part code    | WLL<br>ton | Length<br>m | Cap.<br>kg |
|--------------|------------|-------------|------------|
| PMI0015-2000 | 0.15       | 2           | 150        |
| PMI0015-2500 | 0.15       | 2.5         | 150        |
| PMI0015-3000 | 0.15       | 3           | 150        |
| PMI0015-3500 | 0.15       | 3.5         | 150        |
| PMI0015-4000 | 0.15       | 4           | 150        |
| PMI0015-4500 | 0.15       | 4.5         | 150        |



| PMI0015-5000 | 0.15 | 5   | 150 |
|--------------|------|-----|-----|
| PMI0015-5500 | 0.15 | 5.5 | 150 |
| PMI0015-6000 | 0.15 | 6   | 150 |
| PMI0015-6500 | 0.15 | 6.5 | 150 |
| PMI0015-7000 | 0.15 | 7   | 150 |
| PMI0025-2000 | 0.25 | 2   | 250 |
| PMI0025-2500 | 0.25 | 2.5 | 250 |
| PMI0025-3000 | 0.25 | 3   | 250 |
| PMI0025-3500 | 0.25 | 3.5 | 250 |
| PMI0025-4000 | 0.25 | 4   | 250 |
| PMI0025-4500 | 0.25 | 4.5 | 250 |
| PMI0025-5000 | 0.25 | 5   | 250 |
| PMI0025-5500 | 0.25 | 5.5 | 250 |
| PMI0025-6000 | 0.25 | 6   | 250 |
| PMI0025-6500 | 0.25 | 6.5 | 250 |
| PMI0025-7000 | 0.25 | 7   | 250 |
| PMI0050-2000 | 0.5  | 2   | 500 |
| PMI0050-2500 | 0.5  | 2.5 | 500 |
| PMI0050-3000 | 0.5  | 3   | 500 |
| PMI0050-3500 | 0.5  | 3.5 | 500 |
| PMI0050-4000 | 0.5  | 4   | 500 |
| PMI0050-4500 | 0.5  | 4.5 | 500 |
| PMI0050-5000 | 0.5  | 5   | 500 |

| PMI0050-5500 | 0.5 | 5.5 | 500   |
|--------------|-----|-----|-------|
| PMI0050-6000 | 0.5 | 6   | 500   |
| PMI0050-6500 | 0.5 | 6.5 | 500   |
| PMI0050-7000 | 0.5 | 7   | 500   |
| PMI0100-2000 | 1   | 2   | 1,000 |
| PMI0100-2500 | 1   | 2.5 | 1,000 |
| PMI0100-3000 | 1   | 3   | 1,000 |
| PMI0100-3500 | 1   | 3.5 | 1,000 |
| PMI0100-4000 | 1   | 4   | 1,000 |
| PMI0100-4500 | 1   | 4.5 | 1,000 |
| PMI0100-5000 | 1   | 5   | 1,000 |
| PMI0100-5500 | 1   | 5.5 | 1,000 |
| PMI0100-6000 | 1   | 6   | 1,000 |
| PMI0100-6500 | 1   | 6.5 | 1,000 |
| PMI0100-7000 | 1   | 7   | 1,000 |
| PMI0160-2000 | 1.6 | 2   | 1,600 |
| PMI0160-2500 | 1.6 | 2.5 | 1,600 |
| PMI0160-3000 | 1.6 | 3   | 1,600 |
| PMI0160-3500 | 1.6 | 3.5 | 1,600 |
| PMI0160-4000 | 1.6 | 4   | 1,600 |
| PMI0160-4500 | 1.6 | 4.5 | 1,600 |
| PMI0160-5000 | 1.6 | 5   | 1,600 |
| PMI0160-5500 | 1.6 | 5.5 | 1,600 |
|              |     |     |       |

| PMI0160-6000 | 1.6 | 6   | 2,000 |
|--------------|-----|-----|-------|
| PMI0200-2000 | 2   | 2   | 2,000 |
| PMI0200-2500 | 2   | 2.5 | 2,000 |
| PMI0200-3000 | 2   | 3   | 2,000 |
| PMI0200-3500 | 2   | 3.5 | 2,000 |
| PMI0200-4000 | 2   | 4   | 2,000 |
| PMI0200-4500 | 2   | 4.5 | 2,000 |
| PMI0200-5000 | 2   | 5   | 2,000 |
| PMI0200-5500 | 2   | 5.5 | 2,000 |
| PMI0200-6000 | 2   | 6   | 2,000 |
| PMI0250-2000 | 2.5 | 2   | 2,500 |
| PMI0250-2500 | 2.5 | 2.5 | 2,500 |
| PMI0250-3000 | 2.5 | 3   | 2,500 |
| PMI0250-3500 | 2.5 | 3.5 | 2,500 |
| PMI0250-4000 | 2.5 | 4   | 2,500 |
| PMI0250-4500 | 2.5 | 4.5 | 2,500 |
| PMI0250-5000 | 2.5 | 5   | 2,500 |
| PMI0320-2000 | 3.2 | 2   | 3,200 |
| PMI0320-2500 | 3.2 | 2.5 | 3,200 |
| PMI0320-3000 | 3.2 | 3   | 3,200 |
| PMI0320-3500 | 3.2 | 3.5 | 3,200 |
| PMI0320-4000 | 3.2 | 4   | 3,200 |
| PMI0320-4500 | 3.2 | 4.5 | 3,200 |

| PMI0320-5000 | 3.2 | 5   | 3,200 |
|--------------|-----|-----|-------|
| PMI0400-2000 | 4   | 2   | 4,000 |
| PMI0400-2500 | 4   | 2.5 | 4,000 |
| PMI0400-3000 | 4   | 3   | 4,000 |
| PMI0400-3500 | 4   | 3.5 | 4,000 |
| PMI0400-4000 | 4   | 4   | 4,000 |
| PMI0400-4500 | 4   | 4.5 | 4,000 |
| PMI0400-5000 | 4   | 5   | 4,000 |